CONS. 4047 REV. 10/60

## MICHIGAN DEPARTMENT OF CONSERVATION FORESTRY DIVISION

## LAND CORNER RECORD

T. 40 N.R. 18W

		COUNTY
DESCRIPTION OF CORNER	4 Corner North side Section 3 on 4th Correction Line	
CORNER HONUMENT	1" Iron Pipe with 4" Brass Cap.	
DATE MONUMENT PLACED AND		
WITHESSES TO CORNER	7" Cedar (±S BT) S 77°W 11½ links	
N	9" Cedar (4S BT) S 73°E 13½ links	
3'	AND	

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was established midway and on line between closing corners to East and West.

SURVEYOR'S SEAL

SIGNED Silly & Suckles DATE January 31, 1962

REGISTERED LAND SURVEYOR
Billy D. Buckler