SECTION

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

Approved By Delta County
Land Survey Remonumentation
Peer Group Under Act 345 Of P.A. Of 1990 On Acoust 30, 199 8
P.A. Of 1990 On Stepula 30, 199 8
Neut Shundling
acting Chairman

ALPHA A

For corners in DELTA	Located In:	Corner Code ##	
1. Public Land Survey	T <u>40 N</u> R <u>13 W</u> T R T R T R	B-1 & B-3	13:40 sink PM 100 9 117 916/104 C Thus
Property Controlling in Section	S T R S T R		the stranger of the state of
3. Miscellaneous Property in Sec.	S T R S T R		Register of Deeds Stamp & File Number
5 Private Claims	B-1 [N1/4 COR SEC 1] B-3 [N1/		A B C D E F G H I J K L M
do hereby certify that under rein lines 1 and 2 above were current manual of survey inst Management or by a decree of above were in conformance v. Court of Law; established, expressed below:	_ , in a field survey on	A. of 1970, the corner points mentic and rules therefore as required in artment of the Interior, Bureau of L ner points mentioned in lines 3, 4 a d of Land Surveyors or by a Decree 2-monumented. recovered. found	oned 6 18 17 16 15 14 13 14 13 14 15 14 15 14 15 14 15 14 15 15 15 15 15 15 15 15 15 15 15 15 15
NOTE: Not more than 4 on this certificate	corners, all in the same town a e.	and range, may be recorded	11 12 31 32 33 34 35 36
A. Description of origina	l monument and accessories a	.nd/or subsequent restoration:	

- B-3 [N1/4 COR SEC. 7] A.MERRYWEATHER, D.S. 1848 HEMLOCK 20° CORNER TREE (W. PINE 16°-M65'E-23 LINKS)
 - NO RECORD EVIDENCE OF SUBSEQUENT CORNER RECOVERY AND/OR RESTORATION

B-1 [N1/4 COR SEC. 1] NOT SET IN ORIGINALS

NO RECORD OF SUBSEQUENT CORNER ESTABLISHMENT

- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
- B-1 [N1/4 COR SEC. 1] NO CORNER EVIDENCE FOUND. REESTABLIHED CORNER POSITION AT MIDPOINT BETWEEN AND ON LINE WITH SECTION CORNERS 1/2 MILE EAST & WEST.
- B-3 [N1/4 COR SEC 7] NO CORNER EVIDENCE FOUND, REESTABLISHED CORNER POSITION AT MIDPOINT BETWEEN AND ON LINE WITH SECTION CORNERS 1/2 MILE EAST & WEST.



- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
 - B-1 SET BERNTSEN AINB30 ALUM MONUMENT W/A 31/41 CAP STAMPED TO ID THE CORNER POSITION.

CEDAR 12" SPRUCE 05" N57°W N10°E S56°E 22.90 40.90 27.62'

CEDAR 06" SPRUCE 07* \$71°W

SURVEY MONUMENT SIGN POST

SOUTH 1.81' (TO FACE)

B-3 SET BERNTSEN AINB30 ALUMN MON. W/A 31/4" CAP STAMPED TO ID THE CORNER POSITION.

HEMLOCK 128

HEMLOCK 10"

HEMLOCK 12"(TWIN)

Y.BIRCH 11""

SURVEY MONUMENT SIGN POST

M30,E 28,631 S30°E

S31°W

N72°W 28,661 NORTH

Signed by

14.62'

13.71

25.60'

1.30' (TO FACE)

NOTE: BEARINGS TO REFERENCE OBJECTS ARE MAGNETIC-DISTANCES ARE TO A WAIL W/A DELTA COUNTY REFERENCE TAG, UNLESS OTHERWISE NOTED.

Surveyor's Michigan License No. 16926