## OCT 2 6 1995

## COMMISSION

Approved by Delta County
Land Survey Remonumentation
Peer Group Under Act 345 Of
P.A. Of 1990 On Lane 6, 1995

ATE The Helmelm
1970 Cetting Chairman

LAND CORNER RECORDATION CERTIFICATE

Foi	r corners in	Filing Keq	juirement of Act 74, Mich. P.A	A. 1970 /
	DELTA	Located in:	Corner Code ##	. *
	(County)			
1.	Public Land Survey	T 40 N R 19 W		Recorded JUN 13 1995
		T R T R		The state of the s
		T R	•	9:00 o'clock.M. in Liber 8 Page 63
2.	Property Controlling	S T R	i i	Daita County, Michigan Reg. of Deeds.
3.	in Section Miscellaneous	S T R S T R	i.	•
•	Property in Sec.	S T R		Register of Deeds Stamp & File Number
1	Lot No	Recorded Plat		
	Private Claims			
		G-7 [NW COR SEC 22] G-8 [	W1/4 COR SEC 22]	2 5 5 4 3 2 1
				4 7 8 9 10 11 12
ι, _			ECEMBER . 19 94	. 5
			P.A. of 1970, the corner points mentions and rules therefore as required in	
	•		epartment of the Interior, Bureau of L orner points mentioned in lines 3, 4 ar	
abo	ove were in conformance w	rith the rules of the Michigan Boa	ard of Land Surveyors or by a Decree	of a 20 21 22 23 22 25
-	urt of Law; established, pressed below:	re-established, monumented.	re-monumented, recovered, found	10 30 29 28 27 26 25
NC	OTE: Not more than 4	corners, all in the same tow	n and range, may be recorded	11
	on this certificate	<b>.</b>		12 31 32 33 34 35 36
Α.	Description of original	monument and accessories	and/or subsequent restoration:	13
	D.A.BROTHERTON-190 M.S.McNABB-1925-ST T.OBRIEN-FOUND I.P	9-IDENTIFIED FROM "ORIGINALS AKE & BT'S FOUND IN PLACE SE' . & STAKE IN PLACE NOTED NEW	'-SET NEW STAKE FROM WHICH (CEDA. TIRON PIPE	LINKS) (HEMLOCK 10"-N30°W-06 LINKS) R STUMP 12"-S7°E-18.8") (CEDAR STUMP 14"-N65°E-19 2 OF LXCR'S ON PAGE 253 ON 2/12/79
3.	Description of corner G-7 [NW COR SEC, 22] For	evidence found and/or meth DUND IN PLACE 1-1/4" I.P. IDI	OOD POST & IRON PIPE "NO WIT'S  od applied in restoring or reesta  ENTIFIED SAME FROM BOTH OF O'BRI	blishing corner: EN'S CEDAR BT'S AS
	OF THE ORIGINAL CO	RYER.	S A CAREFUL & FAITHFUL PERPETUAT	E OF MICH
	THAT FOUND IN PLACE		PE. IDENTIFIED EXISTING MONUMENT F MCNABB'S ROAD ALIGNMENT SURVEY	
Э.	G-7 SET, OVER EXISTING CEDAR 08" SPRI N42'E SO		ies established to perpetuate loc ALUMN MON. W/A 3-1/4" CAP STAMP CEDAR 10" SURVEY MONUNE S11°E NOR 62.41' 2.95' (To	ED TO ID THE CORNER POSITION. NT SIGN POST TH
		MONUMENT, A BERNTSEN AINB30 i ER IS IN A LARGE CLEAR CUT AI	ALUUN MON. W/A 3-1/4" CAP STAMPEI REA SURVEY MONUMENT SIGN PO WEST 2.38' (TO FACE)	
2:~	NOTE: BEARINGS TO REFE	RENCE OBJECTS ARE MAGNETIC-D.	ISTANCES ARE TO NAIL W/A DELTA CO	OUNTY REFERENCE TAG, UNLESS OTHERWISE NOTED.
	· · ·	16421	Date	11-6-3
) UI	rveyor's Michigan Licen	SE INU. 70720	iggo 8 PACE 63	FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN 28, 1 REVISED MAY 14, 1 REVISED JAN., 1