## SURVEY & REMONUMENTATION

**JAN 1** 4 1998

## **SECTION**

## LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

Approved By Delta County	
Land Survey Remonumentation	
Peer Group Under Act 345 Of	
P.A <u>. Of</u> 1990 On <u>/2//8</u> , 199 <u>/</u>	2
Whel Schmeling	L
A. V. Chairman	ſ

For corners in DELTA (County)	Located In:	Corner Code ##	Dec 191997
Public Land Survey	T <u>40N</u> R2 <u>4N</u> T B	G-4 & H-5	9:00 AM 26.4
in Section 3. Miscellaneous	T R T R S T R S T R S T R		Register of Deeds Stamp & File Number
4. Lot No, Rec	corded Plat		A B C D E F G H   J K L
5. Private Claims G-4 [1/4 COR COMMON TO SEC'S	9/10] H-5 [1/4 COR CO	OMMON TO SEC'S 10/15]	2 6 5 4 3 2 1 3
do hereby certify that under requi in lines 1 and 2 above were in courrent manual of survey instruct Management or by a decree of a Cabove were in conformance with the Court of Law; established, reservessed below:  NOTE: Not more than 4 corresponding to this certificate.	onformance with regulations and tions of the United States Depart ourt of Law and/or that the corner the rules of the Michigan Board of established, monumented, re-re-	of 1970, the corner points mentioned rules therefore as required in the ment of the Interior, Bureau of Lair points mentioned in lines 3, 4 and f Land Surveyors or by a Decree on numented, recovered, found	ne nd 7
A Description of original mo	onument and accessories and	i/or subsequent restoration:	13
			-17 LINKS)(TAMARACK 12"-N88"W-32 LINKS) POST FROM SAME - CEDAR S2"E 11.6'
M.P. DAVIS 1988 - SET 5/		CAP ON NORTH EDGE OF COUNTY R	27 LINKS)(CEDAR 16*-S83*E-30 LINKS) DAD - ESTABLISHED FROM EXISTING
ALSO POSSIBLE REMAINS OF	: 9/10] FOUND THIS DATE WOOD F ORIGINAL TAMARACK WITNESSES	POST AND MEAD WOODLANDS CEDAR	VITNESS.
DAMAGED BY ROAD GRADING.		3 1988 REBAR AND ALUMN CAP - C AS BEING THE BEST AVAILABLE EV CR.	AP BADLY LAND SURVEYOR
· · · · · · · · · · · · · · · · · · ·	ERNISEN AINB36 ALUMN MONUMENT	PW/A 3 1/4° ALUMN CAP STAMPED VEY MONUMENT SIGN POST FENC	
	18" REBAR (6" BELOW GRADE) W CEDAR 11" CEDAR 5" SUF N78"W S15"E 28.10' 25.43'	V/A 3 1/4" ALUMN CAP STAMPED T VVEY MONUMENT SIGN POST NORTH 1.88' TO FACE	D ID THE CORNER POSITION.
NOTE: BEARINGS TO REFERENCE	OBJECTS ARE MAGNETIC & DISTAN	ICES ARE TO A NAIL W/A REFEREN	CE TAG UNLESS OTHERWISE NOTED.
Signed by	Speis	Date	2/4/97
Surveyor's Michigan License	No. <u>16926</u>		DRM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 19 REVISED MAY 14, 19 REVISED JAN., 19