

MICHIGAN  
DEPARTMENT OF CONSERVATION  
FORESTRY DIVISION

# LAND CORNER RECORD

T. 41 N.R. 18W


Delta COUNTY

DESCRIPTION OF CORNER Section Corner for sections 35/36 on 4th correction line.

CORNER MONUMENT 1" Iron Pipe with 4" Brass Cap.

DATE MONUMENT PLACED AND WITNESSED 7-11-61

WITNESSES TO CORNER..... 5" Cedar (S36) (NBT) N45°E 38 links



6" Cedar (S35) (NBT) N29°W 42 links

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was re-established by single proportioned measurement between  $\frac{1}{4}$  to West and C.C. for Secs. 1 and 2, T40N, R18W.

SURVEYOR'S SEAL

SIGNED Billy D. Buckler DATE January 31, 1962  
REGISTERED LAND SURVEYOR  
Billy D. Buckler