LAND CORNER RECORDATION CERTIFICATE FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

FOR CORNERS OF -:	LOCATED IN-:	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY	T S., R W.	
2. PROPERTY CONTROLL- 1	4 ,T. 41N N. R. 22W W.	14, 1
3. MISCELLANEOUS PROPERTY IN SECTION	,T	

4. LOT NO. ______, RECORDED PLAT_

5. PRIVATE CLAIMS ____

REGISTER OF DEEDS STAMP AND
FILING NUMBER

Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on________, 19______, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

A. Description of original monument and accessories and/or subsequent restoration:

14 - South 1/16 Cor. on the East Sec. line of Sec. 14; not previously established.

1 - West 1/16 Cor. on the North Sec. line of Sec. 14; not previously established.

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

14 - Set M.P.O.L. between the East 1/4 Cor. and the S.E. Sec. Cor. of Sec. 14.

1 - Set M.P.O.L. between the North 1/4 Cor. and the N.W. Sec. Cor. of Sec. 14.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

- 14 D.N.R. Monument; 5" Cedar 887^{0} W 21.1'; 10" Cedar 860^{0} W 36.9'; 7" Balsam 888^{0} E 19.95'; 11" Spruce 823^{0} E 12.05'; right bank of Tacoosh River North 822^{0} L.
- 1 D.N.R. Monument; 4" Balsam Fir S42°E 27.4'; 5" R. Pine S53°W 70.2'; 10" R. Pine S84°W 60.5'; 4" R. Maple N22°E 31.9'.

SIGNED BY Lavil B. Balbett

DATE_ 9-15-83