## LAND CORNER RECORDATION CERTIFICATE

## FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

DELTA

FOR CORNERS OF -:	LOCATE	D IN-:		CORNER CODE NUMBER	
1. PUBLIC LAND SURVEY	т. 41	N. R. 22	E. W.	K-4	
2. PROPERTY CONTROLL- ING IN SECTION—	.T	N. S., R	E. W.		
3. MISCELLANEOUS PROPERTY IN SECTION —	,T	N. S., R.	E. W.		•
4. LOT NO , REC	CORDED PLA	Т			
5. PRIVATE CLAIMS					REGISTER OF DEEDS STAMP AND

A. Description of original monument and accessories and/or subsequent restoration:

K-4 - East 1/4 corner of Section 11; M. McNabb - 1917 - established on old line correct BT (Poplar 3-N40°E - 16.5'; Poplar 2-South-17'.

J −

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

K-4 - Set on line between the N.E. & S.E. sec. corners of Section 11, but not at mid-point. Notes of the original Gov't survey indicate that this corner was set 15 lks. south of a creek and mid-point would fall on high ground North of the creek. This corner was, therefore, set at 2693.7 ft. from the N.E. Section corner and 2653.87 ft. from the S.E. sec. corner. This still places the corner North of the present creek position but it is 15 lks. South of an older creek channel and is at the most northerly position possible to fit the original survey record. M. McNabb shows a measurement of 2688.8 ft. for the North 1/2 of this section line in 1917 but he did not measure the South 1/2.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

K-4 - <u>l" pipe, 4" aluminum cap;</u> 6" Twin Red Maple - N67°W - 23.8'; 16" W. Birch - N35°W - 23.3'; 9" R. Maple - N34°E - 33.9'; 6" Balsam - S06°E - 55.6'.

	٦.	
SIGNED BY Karil B. Balbitt	DATE	8-12-82
03550		e <del>e t</del> erre d'article de la company de la c

1