SURVEY & REMONUMENTATION

JAN 1 4 1998

SECTION

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

Approved By Delta County
Land Survey Remonumentation
Peer Group Under Act 345 Of

	On 12/18	
Alex	Dehmel	ling
	Chairman	<i>-</i>

For	r corners in DELTA	Located In:	Corner Code ##		
	(County)			Dec 1	9 1997
1.	Public Land Survey	T <u>41 N R 23 W</u>	H-11	المستحديدة عاد الباليلاكام	am
		T Ř		a <u>9:00</u>	253
		T R		8)
_		T R		premier c	- Andrews
2.		T R		Land a second	•
_		TR			
3.		T R T R		Register of Deeds S	Stamp & File Number
	Property in Sec. S	· n			<u> </u>
4.	Lot No, Record	ied Plat		A B C D	E F G H I J K L M
	Private Claims				
	H-11 N1/4 C	OR SEC 34 J-11 N1/4 C	OR SEC 35	2 - 6 5	<u></u> 41-1-
				3	
	N B BANTO		MIV	4 - 7 - 4	9 10 11 12
I, _			4 of 1070 the payment sints man		
	hereby certify that under requirem lines 1 and 2 above were in confe				16-15-14-13-
cur	rent manual of survey instructions	s of the United States Dep	artment of the interior, Bureau o	fLand 7	
Mai	nagement or by a decree of a Cour	t of Law and/or that the cor	ner points mentioned in lines 3, 4	and 5 8 19 20	21 22 23 24
abo	ove were in conformance with the uurt of Law; established, re-esta	rules of the Michigan Boar Iblished monumented re	d of Land Surveyors or by a Decr	ee of a	
	urt of Law; established, fe-esta pressed below:	iononea, monumentea, n	,	10 30 29	28 27 26 25
	TE: Not more than 4 corners	s, all in the same town	and range, may be recorded	11	
•	on this certificate.		<u>.</u> , ,	12 31 32	33 34 35 36
				13	
A.	Description of original monu				
			OOD POST (BIRCH 08"-S20°W-23		
			AD-NO CORNER TO BE FOUND-SET S%OOD 14" N40°W 60.0' & MAPLE		CURNERS-NU BI'S NUIED.
	DELIA COUNTY ROAD COMM	1991AU-1941-LA 1804-899	SHOUD IS NOU R OU.U & MAPLE	1 12" AG E \$2.0"	
	3-11 [N1/4 COR SEC 35] A ME	PRYWEATHER D S -1947-WO	OD POST (HEMLOCK 12"-S38°E-28		OG LINKS)
			DAD-STAKE IN PLACE (HEMLOCK		
		ISSION-1947-FD IRON-NO	•	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	
В.	Description of corner eviden				
			PIPE, NO EVIDENCE OF ROAD CO TH ROAD COMMISSION RECORDS. A		OF MICH
			SHMENT OF THE POSITION OF THE		Je me
	DWELL NO DELEG Y OVICE	de a faithful helotabli	Similar of the rootston of the	. Unidikal bunken.	A P O
	J-11 [N1/4 COR SEC 35] FOUN	D IN PLACE & IN POOR CO	NDITION A 1/2" IRON PIN IN AS	PROXIMATE CENTER LINE	6 M. P.
			NT FENCE LINE (DOWN & IN POOP		DAVIS
	NO EVIDENCE OF CRAIG'S	1900 BT'S FOUND, PROPO	RTIONAL DISTANCE TO CORNERS 1	/2 WILE E & W MATCHES	LAND ST. VEYOR
	WELL WITH RECORDS OF C	RAIG.			16926
					EPEN SUIT
		·			FALSE
C.	Description of monument for	corner and accessorie	s established to perpetuate I	ocating the position of the	corner:
	H-11 SET, OVER EXISTING MON	UMENT, A 5/8" X 18" REB	AR W/A 31/4" ALUM CAP STAMPEC	TO ID THE CORNER POSITION	
		PLE 12" MAPLE 12"		Y MONUMENT SIGN POST	
		48°E S51°W	\$36°E	N85°W	
	44.13' 6	0.32' 68.83'	70.93'		
	1_11 DEDLACED EXICTING NAME	אַנבאָד עי/ג בּ/סַװ ע נּסַמּ מרח. וובאַד עי/ג בּ	AR W/A 31/4" ALUM CAP STAMPEC	TO IT THE PARMED PARTITION	
		MENI W/A 0/8" X 10" RE8 PLE 10" MAPLE 05'		Y MONUMENT SIGN POST	•
		13°E S25°E	S24°W	MO3,E	
		6.90' 70.02'		28.12' (TO FACE)	
			·	• - · ·/	
	NOTE: BEARINGS TO REFERENCE	OBJECTS ARE MAGNETIC &	DISTANCES ARE TO A NAIL IN T	THE CENTER OF THE OBJECT, U	NLESS OTHERWISE NOTED.
	Pho Il.	.:		17/alan	•
	ined by	1	Date	14/9/97	
Sur	rveyor's Michigan License No.	16926		CORM ADDROVER OF SHALLOW ATTER	IDARD OF LAND SURVEYORS, JAN. 28. 1971
			e.	FURN AFFRUYEU BI MILINISAN SIALE E	BUARD OF LAND SURVEYORS, JAN. 28. 197 REVISED MAY 14, 197: REVISED JAN., 198: