


STATE OF MICHIGAN  
DEPARTMENT  
OF  
NATURAL RESOURCES

LAND CORNER RECORD

Delta COUNTY  
T 41 N R 23 W

DESCRIPTION OF CORNER Section corner for sections <sup>2/1</sup> 11/12  
CORNER MONUMENT 1" iron pipe with 4" aluminum cap  
DATE MONUMENT PLACED AND WITNESSED 5/23/69, F. J. Bray  
WITNESSES TO CORNER..... 12" tamarack (S.12) (NBT) S 02° E, 139½ links



7" tamarack (S.11) (NBT) S 74° W, 56 links  
AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was reestablished by measurement north and east to stream and checks well with distances of survey made by M. McNabb in 1908. No original evidence found.

SURVEYOR'S SEAL

DISTRIBUTION:

SIGNED

Frank J. Bray  
REGISTERED LAND SURVEYOR  
Frank J. Bray

DATE

12/12/69

County Courthouse  
Area Forester (Regions I & II)  
District or Region Surveyor  
Forestry Div., Lansing

R 4047  
Rev. 10/68