STATE OF MICHIGAN DEPARTMENT OF NATURAL RESOURCES

LAND CORNER RECORD

		Delta	COUNTY
		T 41 N	R23 W
DECODED TANK OF ACRUSE	Section corner for sections	8/9	
DESCRIPTION OF CORNER	Section corner for sections	11/70	
CORNER MONUMENT	1/2" iron rod		
DATE MONUMENT PLACED AND WITNESSED 7/10/69, F. J. Bray			
WITNESSES TO CORNER 10" Corner fence post, north, 01 link			
N 0 1 6	5" Cedar (S.16) (NBT) S 79 ⁰	E, 71 links	
	AND		
CIRCLE CORNER REGISTERED			

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was rewitnessed as set by unknown party. Old rotted scribed wood post and 1/2" iron rod at fence corner. No original evidence found.

SURVEYOR'S SEAL

DISTRIBUTION:

SIGN

SIGNED FREGISTERED LAND SURVEYOR

DATE 12/12/69

Frank J. Bray

County Courthouse Area Forester (Regions I & II) District or Region Surveyor Forestry Div., Lansing