## STATE OF MICHIGAN DEPARTMENT OF NATURAL RESOURCES

## LAND CORNER RECORD

		COUNTY
		T 41 & 42 N R 23 W
DESCRIPTION OF CORNER	Section corner for sections	35/36 T 42N R23W 2/1 T 41N R23W
CORNER MONUMENT	1½" I.D. x 30" iron pipe	
DATE MONUMENT PLACED AND WITNESSED 5/21/69, F. J. Bray		
WITNESSES TO CORNER 4 of blacktop road, north, 20.4 feet		
N 1	Power pole, N 27° E, 74.0 f	'eet
T 4 1 N R 2 3 W	Fence corner post, S 04° E,	25.5 feet
CIRCLE CORNER REGISTERED		

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was replaced from measurements made by M.McNabb, County Surveyor, in 1908 to £ of R.R. now abandoned and with distance on north side of section 1. Fence lines to north and south. No original evidence found. Distances to streams to north and to south check fairly well.

SURVEYOR'S SEAL

DISTRIBUTION:

GNED Trank S. S. A. S. REGISTERED LAND SURVEYOR

DATE 12/11/69

REGISTERED LAND SURV

Frank J. Bray

County Courthouse Area Forester (Regions I & II) District or Region Surveyor Forestry Div., Lansing

R 4047 Rev. 10/68