LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970 PELTA co.

FOR CORNERS OF -:	LOCATED IN -:	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY	_ T. 41 N. R. 23 W.	F-5, G-4, G-5
2. PROPERTY CONTROLL- ING IN SECTION-	N. E. W. S., R W.	
3. MISCELLANEOUS PROPERTY IN SECTION	, T N E.	
4. LOT NO, RECORDED PLAT		
5. PRIVATE CLAIMS	·	

REGISTER OF DEEDS STAMP AND FILING NUMBER

- A. Description of original monument and accessories and/or subsequent restoration:
- South 1/4 corner of Sec. 9; wood post Cedar 12" N60 $^{\circ}$ W 20 1ks.; Tam. 18" S60 $^{\circ}$ E 4 1ks.

East 1/4 corner of Sec. 9; wood post - Birch 10" - S4°E - 8 1ks.; Cedar 7" - North - 11 1ks.

- S.E. corner of Sec. 9; wood post Cedar 12" $N30^{\circ}E$ 15 1ks.; DO 20" $S30^{\circ}W$ 14 1ks.
- B. Description of corner evidence found and/or method applied in restoring or re-establishing corner: Set M.P.O.L. between the S.E. and S.W. section corners of Sec. 9.

Set M.P.O.L. between the N.E. and S.E. section corners of Sec. 9.

- Set by double proportion measurement using section corners 1 mile East 1 mile West 2 miles North and 3 miles South.
- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

1" pipe, 4" alum. cap

5" B. Ash - $865^{\circ}E$ - 11.0'; 11" Cedar - $817^{\circ}E$ - 32.7'; 9" Cedar - $843^{\circ}W$ - 14.2'; 8" W. Birch - $846^{\circ}W$ - 28.3'.

4" Cedar - $N10^{\circ}W$ - 15.24'; 4" Cedar - $N21^{\circ}W$ - 37.53'; 6" Cedar - $N23^{\circ}W$ - 48.03'; 3" R. Maple - $S2^{\circ}W$ - 12.97'.

5" Balsam - $N49^{\circ}E - 43.0$ '; 4" R. Maple - $S16^{\circ}W - 42.4$ '; 9" Cedar - $S14^{\circ}E - 32.8$ '; 6" R. Maple - $N29^{\circ}W - 27.2$ '.

SIGNED BY () OR R. OO, of

15170 12-23-81