

STATE OF MICHIGAN  
DEPARTMENT  
OF  
NATURAL RESOURCES

LAND CORNER RECORD


Delta COUNTY  
T 41 N R 24 W

DESCRIPTION OF CORNER 1/4 corner for sections  $\frac{5}{8}$

CORNER MONUMENT 1" iron pipe with 4" aluminum cap

DATE MONUMENT PLACED AND WITNESSED 6/30/70, F. J. Bray with M. Conley

WITNESSES TO CORNER..... 7" Cedar (1/4 S) (NBT) S 16° E, 13.9'



13" Cedar (1/4 S) (NBT) S 81° E, 14.7'

6" Cedar stump (BT) S 32° E, 19.7'

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was shown to me by Forester Conley. Cedar to NE, overgrowth of scribe mark, is down and in bad condition. Rotted stump bottom for spruce to SW. An old down scribe post and more recent post in proper position. Signature trees in vicinity. Cedar to SE scribed B.T.

SURVEYOR'S SEAL

DISTRIBUTION:

SIGNED

Frank J. Bray  
REGISTERED LAND SURVEYOR  
Frank J. Bray

DATE

7/14/70

County Courthouse  
Area Forester (Regions I & II)  
District or Region Surveyor  
Forestry Div., Lansing

R 4047  
Rev. 10/68