LAND CORNER RECORDATION CERTIFICATE FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

45

	FOR CORNERS OF -:	LOCATED IN -:	CORNER CODE NUMBER	
	I. PUBLIC LAND SURVEY	T N	E. W.	
	2. PROPERTY CONTROLL- 17 ING IN SECTION	,T. 41 N. R. 24	E. 2, 7, 14	
	3. MISCELLANEOUS PROPERTY IN SECTION		E.	
	4. LOT NO, RECORDED PLAT			
	5. PRIVATE CLAIMS			REGISTER OF DEEDS STAMP AND
	David B. Babbitt	do hasaby ca	erify that under requirements of	P. A. 74 Michigan D. A. of 1070
	I, David B. Babbitt do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above (identified with circles on index code diagram—over) were, in a field survey on December 22 19.78, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on 19, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of			
	law:			
2	A. Description of original monument and accessories and/or subsequent restoration: - E. 1/16 corner on the North section line - Sec. 17; not previously established.			
7	- N. 1/16 corner, East line Sec. 17; not previously established.			
14	- 8. 1/16 corner on the	East line of Sec	. 17; not previously est	ablished.
2	B. Description of corner evide	nce found and/or method	applied in restoring or re-estab	lishing corner:
7	- Set M.P.O.L. between the N & corner and the N.E. Section corner of Sec. 17. - Set M.P.O.L. between the N.E. section corner and the E & corner of Sec. 17.			
		•	nd the S.E. Section corn	
	- Des Milions Desweet	one n. 4 corner &	id the p.p. Section COM	er or sec. 1(.
AL	C. Description of monument for L - 1" pipe, 4" aluminum	or corner and accessorie	es established to perpetuate loc	ating the position of the corner:
2	- 5" Tam S33"W - 10. N61°E - 8.5'.	7'; 5" Tam S72 ⁰	E - 8.7'; 7" Tam N20°	W - 17.2'; 4" Tam
7	- 8" Tam N16°W - 156.55'; 4" Birch - N15°W - 156.50'; 3" Balsam - S1°E - 135.90'; 6" B. Spruce - N60°E - 148.60'.			
14	- 9" Cedar - N69°E - 8.60'; 4" S. Maple - N40°E - 17.50'; 8" Cedar - N21°W - 27.25'; 9" Cedar - N79°W - 23.50'.			
	SIGNED BY		DATE	
	SURVEYOR'S MICHIGAN REG	SISTRATION NO		(SEAL)
	FOR STATE AND UNITED ST	ATES AGENCIES:		•
	SIGNED BY DATE			
	APPROVED AND SIGNED BY.	$\langle 1 \rangle \langle 0 \rangle \langle 0 \rangle$	Bellett DATE	12-27-78
	SURVEYOR'S MICHIGAN REGI	STRATION NO.	21558	

FORM APPROVED BY MICHIGAN STATE BOARD OF REGISTRATION, JAN. 28, 1971
DISTRIBUTED BY MICHIGAN SOCIETY OF REGISTERED LAND SURVEYORS

*.

Form No. ML M735 POUDLEGAY BROS. & CO., RALAMAZOO, MICH.