

## OCT 2 6 1995

## COMMISSION

Approved By Detta County Land Survey Remonumentation Peer Group Under Act 345 Of 0(1990 On 2012 22, 199.5

clive Chairman

unel

## LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

For	corners in DELTA			1						
	(County)	Located In:	Corner Code ##			**				
1.	Public Land Survey	T <u>41 N</u> R <u>19 N</u> T R T R		Recordedat 9:00 o'clos						
2.	Property Controlling in Section	S T R S T R		Delta County,	Michiga		Mariante & A. C. C. C.	5. <b>V</b> 3 E4		
3.	Miscellaneous	S T R		Registe	ar of D	2 shae	lama 2	Eila	Numbe	
	Property in Sec.	\$ R		Tiegiste				riie		<del></del>
4.	Lot No , I	Recorded Plat			<b>А</b> В	C D I	: FG	Н		1 14
				··	٦		<del></del>	<del>-i'</del>		
in li	M.P. DAVIS ereby certify that under re- nes 1 and 2 above were i	. in a field survey on <u>SEPT</u> quirements of P.A. 74, Michigan P. n conformance with regulations	EMBER , 19 95 A. of 1970, the corner points men and rules therefore as required	o , 5 ntioned 6	718181818181818	8-1717	9-16	-15-	—11— —14—	12-
Man abo	agement or by a decree of we were in conformance wi	ructions of the United States Dep a Court of Law and/or that the cor ith the rules of the Michigan Board re-established, monumented, re	ner points mentioned in lines 3, 4 d of Land Surveyors or by a Decr	4 and 5 8	_19	20	-21	-22-		-24
expressed below:					30	-29-	28	<b>-27</b>	-26-	25
NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.							+			+-{
	on and certificate.			12 [	31 <del></del>		_33	_3/	2EL	

- Description of original monument and accessories and/or subsequent restoration: M-12 [E1/4 COR SEC. 36] JOHN BURT, D.S. - 1845 - (TAMARACK 24"-S67°W-06 LINKS) (HEMLOCK 05"-N47°W-17 LINKS) NO RECORD EVIDENCE OF CORNER RECOVERY OF SUBSEQUENT HONUMENTATION
- M-13 [SE COR SEC. 36] JOHN BURT, D.S.-1845- WOOD POST (HEMLOCK 14"-N40°E-09 LINKS) (HEMLOCK 15"-S59°W-20 LINKS) M.S.McNABB - 1920 - ESTABLISHED ON 4TH CORRECTION LINE IN LINE WITH FARM FENCE MORTH. NO WIT'S NOTED, SET IRON STAKE.
- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: M-12 [E1/4 COR SEC 36] FOUND IN PLACE A 2' X 30" GALV IRON PIPE AT JCT OF FARM FENCES NORTH AND WEST. NO OTHER EVIDENCE OF CORNER POSITION FOUND, ACCEPTED EXISTING MONUMENT AS BEING THE BEST AVAILABLE EVIDENCE AS TO THE POSITION OF THE ORIGINAL CORNER.
  - N-13 [SE COR SEC 36] FOUND IN PLACE 3/4" IRON PIPE. CORNER POSITION FALL IN AN OPEN FARM FIELD, NO OTHER EVIDENCE AVAILABLE, DISTANCES E & W TO ADJOINING CORNERS CHECK WELL WITE THE RECORD. ACCEPTED EXISTING MONUMENT AS THE BEST AVAILABLE EVIDENCE AS TO THE LOCATION OF THE POSITION OF THE ORIGINAL CORNER.



C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: M-12 REPLACED EXISTING MONUMENT W/A BERNTSEN AINB30 ALUMN MONUMENT W/A" 31/4" ALUMN CAP STAMPED TO 1D THE CORNER POSITION.

MAPLE 24"

CEDAR 11"

SURVEY MONUMENT SIGN POST

NOTE: FARM FIELDS IN NE & SE QUADRANTS

S40°W 36.571 N25°W 56.531

WEST 2.12' (TO FACE) NO OTHER WIT'S AVAILABLE.

M-13 SET, OVER EXISTING MON, A BERNTSEN AINB30 ALUMN MONUMENT W/A 31/4" ALUMN CAP STAMPED TO ID THE CORNER POSITION. SURVEY MONUMENT SIGN POST NOTE: FARM FIELDS IN ALL QUADRANTS

SOUTH

NO OTHER WIT'S AVAILABLE

2.35' (TO FACE)

NOTE: BEARINGS TO REFERENCE OBJECTS ARE MAGNETIC-DISTANCES ARE TO A NAIL W/A DELTA COUNTY REFERENCE TAG, UNLESS OTHERWISE NOTED.

Signed by . Surveyor's Michigan License No. 16926 Date

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971