LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

	Delta	Located In:	Corner Code ##									
1.	Public Land Survey .	T R T R T R										
2.	Property Controlling	s <u>11 t42N R22W</u>	3,15									
3.	in Section Miscellaneous Properly in Sec.	S T R S T R S T R	,	Register	of De	eds S	Stamp) & F	ile I	Nun	ıber	
4. 5.	Lot No , F	Recorded Plat		A	B (C D	E F	G	ні	ı J	ĸ	L
J.	Filvate Ciailis			2	- 6	- 5	├ -	1	i —	_2	1	<u> </u>
				3		+	-	+		\dashv	+	- -
	David Rabbitt	in a field august on July	6th 40 87	4	-	- 8	 	+1	0-	1/1	+	-12-
I. David Babbitt , in a field survey on July 6th , 19 87 , do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the					-18		_16		5	 	1	-13-
Cur	rent manual of survey instri	Land 7	+			1-1	\sqcup	\dashv		1		
Mai abo	Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a						21-	-	2—	—23	+	-2 4 -
Cor	Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:					-29	28-		$\frac{1}{2}$	-26	+	25
NOTE: Not more than 4 corners, all in the same town and range, may be recorded					30	Ĭ.	ı					1
on this certificate.					31		 —33—	1_3	4_	35-	_	-36
				13		ĺ	Ĩ	ΙĬ		Ĩ		Ī

A. Description of original monument and accessories and/or subsequent restoration:

For corners in

- 3 North 1/16 corner on the West section line of Section 11. No previous record.
- 15 West 1/16 corner on the South section line at Section 11. No previous record.
- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
 - 3 Set MPOL between the West $\frac{1}{2}$ corner and the NW section corner of Section 11.
- 15 Set MPOL between the South ¼ corner and the SW section corner of Section 11.

- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
- 3 DNR Monument
 10" Spruce N69E 58.5'
 10" Lynn S42E 54.8'
 5" Lynn S 7W 29.1'
 6" B. Ash N40W 39.7'

 15 DNR Monument
 5" Cedar N15E 15.8'
 5" Cedar S65E 17.3'
 12" Cedar S24E 40.2'
 5" B. Ash N69W 10.1'

Signed by Lavil B. Ballett Date

12-3-87

Surveyor's Michigan License No. 21558