LAND CORNER RECORDATION CERTIFICATE

For corners in	Filing Require	ement of Act 74, Mich.	P.A. 1970
Delta (County)	Located In:	Corner Code ≠	
Public Land Survey	T R T R T R T R		
2. Property Controlling in Section	S <u>8</u> T <u>42N</u> R <u>22W</u> S T R	1, 3,	
Miscellaneous	S T R		Register of Deeds Stamp & File Number
Property in Sec.	S T R		register of Deeds Stamp & the Rumber
	Recorded Plat		ABCDEFGHIJKL
do hereby certily that under re in lines 1 and 2 above were in current manual of survey instruments of by a decree of above were in conformance with Court of Law; established, expressed below:	in a field survey on	of 1970, the corner points ment of rules therefore as required ment of the Interior, Bureau of points mentioned in lines 3, 4 Land Surveyors or by a Decre onumented, recovered, four	tioned in the 18 17 16 15 14 13 14 13 15 14 15 14 15 14 15 15 14 15 15 16 15 16 15 16 15 16 15 16 15 16 16 16 16 16 16 16 16 16 16 16 16 16
A. Description of original	monument and accessories and	or subsequent restoration	13 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
1. W 1/16 on the	he north section line S	Section 8. No prev	vious record.
3. N 1/16 corn	er on the west section	line of Section 8.	No previous record.

- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
 - 1. Set MPOL between the north 1/4 corner and the NW section corner of Section 8.
 - 3. Set MPOL between the west 1/4 corner and the NW section corner of Section 8.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

1. DNR Monument 3. DNR Monument 14" r.maple, S75W, 12.5'
4" h.maple, N41W, 9.4'
7" h.maple, N63E, 18.85'
6" h.maple, S45E, 20.3' 12" spruce, N8977, 33.5'
12" cedar, N5W, 31.6'
13" cedar, N49E, 14.7'
7" b.ash, N4E, 23.7'

21558

Surveyor's Michigan License No.

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975 REVISED JAN., 1983