## SURVEY & REMONUMENTATION

MAR 2 1 1997

Approved By Delta County

Land Survey R	lemonumentation
Peer Group U	Inder, Act 345 Of
	<u> 2//2-</u> , 199 <i>6</i>

## COMMISSION

LAND CORNER RECORDATION CERTIFICATE

<b></b> _	For corners in											
⊦or	comers in DELTA	Located Ir	<b>.</b> .	Corner Co	io -/-/							
	(County)	Located if	τ;	Corner Co				. 250	2.0	000		
1	Public Land Survey	r 42	₽ 23 W	A-1 &	A-2		Record		<u> </u>	99 <u>6</u>		
١.	, upilo cario odivoy		R				શં	2:00	o'clcck_	1910	دا	
			R				Liter		_Page	17	7	
2	Property Controlling	S T	R						145 AL.	ب راهه شبکاند		
۷.	in Section	S T					Delta :	Courty, M. Sea.	, ct l'æcs			
3.	Miscellaneous	\$ T	R			Register	of Dee	eds Stamp	& File	Numb	er	
	Property in Sec.	S T	R									
4.	Lot No,	Recorded Plat				<b>_</b>	вс	DEF	g н	1 .	C ! M	
	Private Claims					Ĵ		ŢŤŤ	ŢŢ	i Ţ		
	A-1 [	NW COR S.6] A-Z [W1/	4 COR S. 6]			3	- 6	- 5 - 4 -	3-	2-		
						4	_ 7	- 8 <del> 9 -</del>	  10	11	12	
1	M.P. DAVIS	, in a field survey on	07 JU	LY	, 1996	_ , 5		1 1	+	<u> </u>		
do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the												
cur	rent manual of survey inst	ructions of the United S	States Departme	nt of the Interi	or, Bureau of La	and 7		++-			++	
Mai abo	nagement or by a decree o ove were in conformance w	i a Court of Law and/orti vith the rules of the Mich	nat the corner po igan Board of La	and Surveyors	or by a Decree o	ofa 9	—1'9———	-2021	2 <sup>2</sup> 2	2'3   	<del> </del> 2⁴	
Col	urt of Law; established,	re-established, monur	nented, re-mon	numented, rec	overed, found	as 10		29 28	27	26	25	
	oressed below:  TE: Not more than 4	corners all in the sa	me town and	range may h	e recorded	11		29 20				
110	on this certificate			iongo, may a		12	_ 31	32 -33-	34	35—	36	
						13 L						
Α.	Description of origina A-1 [NW COR S.6] WILL	I monument and acce IAM BURT.D.S1841 -	essories and/o - WOOD FOST (B)	r subsequen [RCH 16]-N45°	restoration: Z-23 LINKS) (B	IRCH 10"-S22	. W-No E	ISTANCE GI	VEN)			
	A-2 [W1/4 COR S.6] WI	E OF CORNER RECOVERY  LLIAM BURT, D.S 184 E OF CORNER RECOVERY	I -WOOD POST (	HENLOCK 10"-	324°E-23 LINKS	) (CEDAR 08*	- <b>X</b> 4 4 ° W-	23 LINKS)	نفدن		<b>La</b> .	
В.			PIPE BY PERSON AND ANCIENT B	KS UNKNOWN. I FENCE LINE NO	CORNER POSIT	ION FROM EXI EVIDENCE VI	STING SIBLE.	ER.	LAND	AVIS SURVE NO. 6926	YOR SURLEY	
	A-2 [W1/4 COR S.6] NO CORNERS 1/2 MILE		D. REESTABLISE	ED CORNER PO	ITION A MIDPO	INT BETWEEN	SECTION		**************************************	****	•	
C.	Description of monum A-1 SET OVER EXISTING FOWER POLE HO N48°W 42.85'	MON A 5/8" X 18" REB LE EAST END CMP SP N57°E	AR W/A 31/4" A RUCE 6" SE S42°E	ALUM CAP STAM PRUCE 5"		CORNER POSIT T SIGN POST H				A MONUI	MENT BOX	
			R W/A 31/4" AI MONUMENT SIGN EAST		D TO ID THE C	ORNER POSITI	ON	· ·				
	65.47'		22.51' (TO FAC	CE)								
	NOTE: BEARINGS TO REF		GNETIC & DISTA	ANCES ARE TO	NAIL IN THE	CENTER OF TH	E OBJEC	T, UNLESS	OTHERWIS	SE NOTI	ED.	
Sic	ned by M.P.A	4U/S			Date <i>[2</i> ]	110/94						
	rveyor's Michigan Licer				. '	-						
	.,				•	FORM APPROVED BY	MICHIGAN	STATE BOARD OF	LAND SURV	ETUKS, JA	nt. 28. 19/1	