

STATE OF MICHIGAN  
DEPARTMENT  
OF  
NATURAL RESOURCES

LAND CORNER RECORD

Delta COUNTY

T 43 N R's 22 & 23 W


T43N 25/30 T43N  
R23W 36/31 R22W

DESCRIPTION OF CORNER Section corner for Sections

CORNER MONUMENT 1" iron pipe with 4" aluminum cap

DATE MONUMENT PLACED AND WITNESSED 9/17/71 F. J. Bray

WITNESSES TO CORNER..... 7" Cedar (S.25) (NBT) N81°W, 35.3'



Power pole, S36°W, 37.2'

12" Cedar (McNabb's BT) N25°W, 66.2'

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was replaced from N.B.T. of Marcus McNabb. Found point of old stake at this location. McNabb noted iron pipe at this corner in 1929, pipe now missing.

SURVEYOR'S SEAL

DISTRIBUTION:

SIGNED

  
REGISTERED LAND SURVEYOR  
Frank J. Bray

DATE

12-9-71

County Courthouse  
Area Forester (Regions I & II)  
District or Region Surveyor  
Forestry Div., Lansing

R 4047  
Rev. 10/68