

STATE OF MICHIGAN
DEPARTMENT
OF
NATURAL RESOURCES

LAND CORNER RECORD

Delta COUNTY


T 43 N R 22W

DESCRIPTION OF CORNER 1/4 Corner for Sections $\frac{7}{18}$

CORNER MONUMENT 1" iron pipe with 4" aluminum cap

DATE MONUMENT PLACED AND WITNESSED 8-22-72 F. J. Bray

WITNESSES TO CORNER..... 7" Cedar (1/2S) (NBT) N 18 W, 14.6'



9" Cedar (1/2S) (NBT) S11 W, 10.4'

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was replaced from point of old down scribed wood post and from
Marcus McNabb's N.B.T. He stated 4 Birch B.T. present in the 1930's.
Birch now down and rotted but overgrowth of faces visible.

SURVEYOR'S SEAL

DISTRIBUTION:

Forestry Division, Lansing

SIGNED

Frank J. Bray
REGISTERED LAND SURVEYOR
Frank J. Bray

DATE

11-24-72