

STATE OF MICHIGAN
DEPARTMENT
OF
NATURAL RESOURCES

LAND CORNER RECORD


Delta COUNTY
T 43 \searrow R 22W

DESCRIPTION OF CORNER $\frac{1}{4}$ Corner for Sections $\frac{9}{16}$

CORNER MONUMENT 1" iron pipe with 4" aluminum cap

DATE MONUMENT PLACED AND WITNESSED 10-30-72 F. J. Bray

WITNESSES TO CORNER..... 12" Cedar ($\frac{1}{4}$ S)(NBT) S 87 W, 9.1'



10" Hemlock ($\frac{1}{4}$ S) (NBT) S 48 E, 8.6'

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was placed midway and on a line between section corners to the east and to the west. Several blazed trees near and old down post.

No original evidence found.

SURVEYOR'S SEAL

DISTRIBUTION:

Forestry Division, Lansing

SIGNED

Frank J. Bray
REGISTERED LAND SURVEYOR
Frank J. Bray

DATE

11-24-72