

STATE OF MICHIGAN
DEPARTMENT
OF
NATURAL RESOURCES

LAND CORNER RECORD

Delta COUNTY


T 43 N R 22W

DESCRIPTION OF CORNER 1/4 Corner for Sections ¹⁸ 19

CORNER MONUMENT 1" iron pipe with 4" aluminum cap

DATE MONUMENT PLACED AND WITNESSED 10-13-72 F. J. Bray

WITNESSES TO CORNER..... # 7" Cedar (1/2S) (NBT) N34° W, 10.4'



6" Cedar (1/2S) (NBT) S 63° E, 11.4'

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was reestablished by single proportioned measurement between section corners to the east and to the west. Rusted Forest Service tag on tree is near. No original evidence found.

SURVEYOR'S SEAL

DISTRIBUTION:

Forestry Division, Lansing

SIGNED

Frank J. Bray
REGISTERED LAND SURVEYOR
Frank J. Bray

DATE

11-17-72