COUNTY

Delta

STATE OF MICHIGAN DEPARTMENT OF NATURAL RESOURCES

LAND CORNER RECORD

	T <u>43 N</u> R 22₩	
DESCRIPTION OF CORNER	East $1/16$ Corner of Sections $\frac{5}{8}$	
	1" iron pipe with 4" aluminum cap	
DATE MONUMENT PLACED AND	WITNESSED 8-7-72 F. J. Bray	
WITNESSES TO CORNER	6" Cedar (E 1/16) (BT) S 71°W, 10.8'	
N 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8	5" Cedar (E 1/16) (BT) N54 E, 4.5'	
	AND	
CIRCLE CORNER REGISTER	ED	
DESCRIPTION IN DETAIL AS	TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.	
White common was not be a		
inis corner was set by pr	roportion from section corner & mile east and & corner	
4 mile west.		
SURVEYOR'S SEAL		
DISTRIBUTION:	IGNED TOTAL DATE 11-17-72 REGISTERED LAND SURVEYOR	
Forestry Division, Lansin	Frank J. Bray ng	
		
	R 4047 Rev. 1/7	72