

STATE OF MICHIGAN
DEPARTMENT
OF
NATURAL RESOURCES

LAND CORNER RECORD


Alger
Delta COUNTY
44
T 43 N R 22 W

DESCRIPTION OF CORNER 1/4 corner for Sections ^{31 T44N-R22W}
6 T43N-R22W

CORNER MONUMENT 1" iron pipe with 4" aluminum cap

DATE MONUMENT PLACED AND WITNESSED June 13, 1972

WITNESSES TO CORNER..... 11" Hemlock (1/4S) (NET) N06°E 31.8'



6" R. Maple (1/4S) (NET) S24°E 21.4'

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was replaced from M. McNabb's notes. From his new B.T. and he found an original B.T. to the northwest which is now a badly rotted birch stump. Down rusted pipe found at corner.

SURVEYOR'S SEAL

DISTRIBUTION:

Forestry Division, Lansing

SIGNED

Frank J. Bray
REGISTERED LAND SURVEYOR
Frank J. Bray

DATE

8-11-72