

STATE OF MICHIGAN
DEPARTMENT
OF
NATURAL RESOURCES
LAND CORNER RECORD

Alger and Delta COUNTY


44
T 43 N R 22 W

DESCRIPTION OF CORNER Section corner for Sections $\frac{32}{54}$ T44N-R22W
5/4 T43N-R22W

CORNER MONUMENT 1" iron pipe with 4" aluminum cap

DATE MONUMENT PLACED AND WITNESSED July 21, 1972 F. J. Bray

WITNESSES TO CORNER..... 12" Cedar (S.32) (NBT) N37°W, 12.4'



16" Cedar (S.5) (NBT) S22°W, 24.9'

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was replaced from a rusted iron pipe set by an unknown party.

Corner checks well with corners in area.

SURVEYOR'S SEAL

DISTRIBUTION:

Forestry Division, Lansing

SIGNED

Frank J. Bray
REGISTERED LAND SURVEYOR
Frank J. Bray

DATE

8-11-72