

STATE OF MICHIGAN
DEPARTMENT
OF
NATURAL RESOURCES

LAND CORNER RECORD

Delta COUNTY


T 13 N R 22 W

DESCRIPTION OF CORNER Section corner for Sections ^{4/3} 9/10

CORNER MONUMENT 1" iron pipe with 4" aluminum cap

DATE MONUMENT PLACED AND WITNESSED July 25, 1972 F. J. Bray

WITNESSES TO CORNER..... 12" Cedar (S.3) (NBT) N17°E, 6.3'



16" Cedar (S.9) (NBT) S48°W, 9.4'

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was replaced from an old wood post. Signature tree nearby blazed approximately 50 years ago. Other blazed trees and U. S. Forest Service location tag face corner.

SURVEYOR'S SEAL

DISTRIBUTION:

Forestry Division, Lansing

SIGNED


REGISTERED LAND SURVEYOR
Frank J. Bray

DATE

8-11-72