## STATE OF MICHIGAN DEPARTMENT OF NATURAL RESOURCES

## LAND CORNER RECORD

	COUNTY
	T <u>43 N</u> R <u>22 W</u>
DESCRIPTION OF CORNER 1/4 corner for Sections 4/3	
CORNER MONUMENT 1" iron pipe with 4" aluminum cap	
DATE MONUMENT PLACED AND WITNESSED July 26, 1972	
WITNESSES TO CORNER Lu Cedar (1/Ls) (NBT) S660	_
5" Gedar (1/LS) (NET) S37 <sup>C</sup>	
AND	
CIRCLE CORNER REGISTERED	
DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.	
This corner was set by proportioned distance between the	ne section corners to the
north and to the south.	
SURVEYOR'S SEAL	
DISTRIBUTION:  SIGNED  REGISTERED LAND SUBMIT  Frank J. Bray	DATE 8-11-72

R 4047 Rev. 1/72