STATE OF MICHIGAN DEPARTMENT OF NATURAL RESOURCES

LAND CORNER RECORD

Del.ta

COUNTY

τ	43 N	R's 22 & 23 W
DESCRIPTION OF CORNER North 1/16 corner for Sections R2		13N 22w
	- 157 L IVE	.en
CORNER MONUMENT 1" iron pipe with 4" aluminum cap		
DATE MONUMENT PLACED AND WITNESSED JULY 11, 1972 F.	J. Bray	7, 4, 4
WITNESSES TO CORNER 4" B. Spruce (N1/16) (BT) N50°	w, 5.51	
5" B. Spruce (N1/16) (BT) N66°	E, 6.91	
AND		
CIRCLE CORNER REGISTERED		
DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDE	NTIFIED OF	R RESTORED.
This corner was placed midway and on line between the section corner to the		
north and 1/4 corner to the south. Old scribed post near.		
SURVEYOR'S SEAL		
DISTRIBUTION: SIGNED REGISTERED LAND SURVEYOR Frank J. Bray Forestry Division, Lansing	DATE	8-11-72
- oredery protection, banking		
		R 4047 Rev. 1/72