

STATE OF MICHIGAN
DEPARTMENT
OF
NATURAL RESOURCES

LAND CORNER RECORD


Delta COUNTY
T 43 N R 22 W

DESCRIPTION OF CORNER 1/4 corner for Sections 29/28

CORNER MONUMENT 1" iron pipe with 4" aluminum cap

DATE MONUMENT PLACED AND WITNESSED 10/6/71 F. J. Bray

WITNESSES TO CORNER..... 8" Cedar (1/8) (NBT) N12°E, 13.1'



11" Y. Birch (1/8) (NBT) S60°W, 2.9'

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was replaced from wood post which was in proper location from two possible B.T.'s to the northeast and to the southwest. Stumps were cut high. Portion of stumps where faces had been are burned and rotted.

SURVEYOR'S SEAL

DISTRIBUTION:

SIGNED

Frank J. Bray
REGISTERED LAND SURVEYOR
Frank J. Bray

DATE

12-9-71

County Courthouse
Area Forester (Regions I & II)
District or Region Surveyor
Forestry Div., Lansing

R 4047
Rev. 10/68