## STATE OF MICHIGAN DEPARTMENT OF NATURAL RESOURCES

## LAND CORNER RECORD

	Delta	COUNTY
•	1 43 K	R 22 W
DESCRIPTION OF CORNER South 1/16 corner for Section	s 28/27	
CORNER MONUMENT 1" iron pipe with 4" aluminum cap		
DATE MONUMENT PLACED AND WITNESSED 9/24/71 F. J. Bray		
WITNESSES TO CORNER 9" Cedar (S1/16) (BT) 117°E,	3.01	
12" Cedar (S1/16) (BT) S12°E,	5.81	
AND		
CIRCLE CORNER REGISTERED		

## DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was placed midway and on line between the section corner to the south and the 1/h corner to the north.

SURVEYOR'S SEAL

DISTRIBUTION:

SIGNED REGISTERED LAND SURVI

Frank J. Bray

DATE \_

12**-**9-71

County Courthouse Area Forester (Regions I & II) District or Region Surveyor Forestry Div., Lansing

R 4047 Rev. 10/68