STATE OF MICHIGAN DEPARTMENT 0F NATURAL RESOURCES

LAND CORNER RECORD

DeltaCOU	INTY
T 43 N R 22	W
DESCRIPTION OF CORNER South 1/16 corner for Sections 22/23	 .
CORNER MONUMENT 2" X 12" reinforcing rod buried in blacktop road	
DATE MONUMENT PLACED AND WITNESSED 9/28/71 F. J. Bray	
WITNESSES TO CORNER 8" Tamarack (S1/16) (BT) N71°W, 43.1'	
12" Tamarack (BT) S67°E, 46.6'	
Ø of blacktop road, east 1.0' AND	
CIRCLE CORNER REGISTERED	

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was placed midway and on line between the section corner to the south and the 1/4 corner to the north.

SURVEYOR'S SEAL

SIGNED REGISTERED LAND SURVEYOR Frank J. Bray

DATE _

DISTRIBUTION:

County Courthouse Area Forester (Regions I & II) District or Region Surveyor Forestry Div., Lansing