STATE OF MICHIGAN DEPARTMENT 0F **NATURAL RESOURCES**

LAND CORNER RECORD

DESCRIPTION OF CORNER South 1/16 corner for Sections 27/26 CORNER MONUMENT 1" iron pipe with 4" aluminum cap DATE MONUMENT PLACED AND WITNESSED 9/29/71 F. J. Bray WITNESSES TO CORNER 7" H. Maple (S1/16) (BT) S34°W, 36.4' 7" H. Maple (S1/16) (BT) N82°E, 64.7'	OUNTY
CORNER MONUMENT 1" iron pipe with 4" aluminum cap DATE MONUMENT PLACED AND WITNESSED 9/29/71 F. J. Bray WITNESSES TO CORNER 7" H. Maple (S1/16) (BT) S34°W, 36.4' 7" H. Maple (S1/16) (BT) N82°E, 64.7'	22 W
DATE MONUMENT PLACED AND WITNESSED 9/29/71 F. J. Bray WITNESSES TO CORNER 7" H. Maple (S1/16) (BT) S34°W, 36.4' 7" H. Maple (S1/16) (BT) N82°E, 64.7'	
7" H. Maple (S1/16) (BT) S34°W, 36.4' 7" H. Maple (S1/16) (BT) N82°E, 64.7'	
7" H. Maple (S1/16) (BT) N82°E, 64.7'	
7" H. Maple (S1/16) (BT) N82°E, 64.7'	
 ²⁰ 	
AND	

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was placed midway and on line between the section corner to the south and the 1/4 corner to the north.

SURVEYOR'S SEAL

SIGNED -REGISTERED LAND SURVEYOR

DATE 12-9-71

DISTRIBUTION:

Frank J. Bray

County Courthouse Area Forester (Regions I & II) District or Region Surveyor Forestry Div., Lansing