STATE OF MICHIGAN DEPARTMENT 0F **NATURAL RESOURCES**

LAND CORNER RECORD

	Del ta	COUNTY
	T43_N	R 22 W
DESCRIPTION OF CORNER North 1/16 corner for Section	ions 27/26	
CORNER MONUMENT 1" iron pipe with 4" aluminum cap		
DATE MONUMENT PLACED AND WITNESSED 9/29/71 F. J. I	Bray	
WITNESSES TO CORNER 8" Elm (N1/16) (BT) S12°E,	44.51	
8" H. Maple (ВТ) S46°E, 48.		
AND		
CIRCLE CORNER REGISTERED		

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was placed midway and on line between the section corner to the north and the 1/4 corner to the south.

SURVEYOR'S SEAL

SIGNED

REGISTERED LAND SURVEYOR

DISTRIBUTION:

Frank J. Bray

County Courthouse Area Forester (Regions I & II) District or Region Surveyor Forestry Div., Lansing