STATE OF MICHIGAN DEPARTMENT 0F NATURAL RESOURCES

LAND CORNER RECORD

DATE MONUMENT PLACED AND WITNESSED 11/4/71 F. J. Bray				Delta	COUNTY	
DESCRIPTION OF CORNER North 1/16 corner for Sections R22W 12/7 R21W CORNER MONUMENT 1" iron pipe with 4" aluminum cap DATE MONUMENT PLACED AND WITNESSED 11/4/71 F. J. Bray WITNESSES TO CORNER 4" Blm (X) (BT) N76°W, 26.5' N 11" Cedar (N1/16) (BT) S82°E, 21.0'			τ.	43 R	R's 21 & 22 W	
DATE MONUMENT PLACED AND WITNESSED	DESCRIPTION OF CORNER	North 1/16 corner f	or Sections	TL3N R22W 12/7		
WITNESSES TO CORNER 4" Blm (X) (BT) N76°W, 26.5' 11" Cedar (N1/16) (BT) S82°E, 21.0' Th3N	CORNER MONUMENT 1" iron pipe with 4" aluminum cap					
11" Cedar (N1/16) (BT) S82°E, 21.0' Th3N	DATE MONUMENT PLACED AND WITNESSED 11/4/71 F. J. Bray					
11" Cedar (N1/16) (BT) S82 E, 21.0"	WITNESSES TO CORNER 4" Bam (X) (BT) N76°W, 26.51					
	N 7	11" Cedar (N1/16) (BT) S82 ⁰ E, 2	1.0'		
/	1 1 21 1	AND				

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was placed midway and on line between the section corner to the north and the 1/4 corner to the south.

SURVEYOR'S SEAL

SIGNED REGISTERED LAND SURVEYOR

DISTRIBUTION:

Frank J. Bray

County Courthouse Area Forester (Regions I & II) District or Region Surveyor Forestry Div., Lansing