
## STATE OF MICHIGAN DEPARTMENT 0F **NATURAL RESOURCES**



## LAND CORNER RECORD

DESCRIPTION OF CORNER North 1/16 corner for Sections 35/36  CORNER MONUMENT 1" iron pipe with 4" aluminum cap  DATE MONUMENT PLACED AND WITNESSED 9/3/71 F. J. Bray  WITNESSES TO CORNER 5" H. Maple (N1/16) (BT) S 35° W, 3.2'  5" B. Ash (N1/16) (BT) S 80° E, 8.3'
CORNER MONUMENT 1" iron pipe with 4" aluminum cap  DATE MONUMENT PLACED AND WITNESSED 9/3/71 F. J. Bray  WITNESSES TO CORNER 5" H. Maple (N1/16) (BT) S 35° W, 3.2'  N
DATE MONUMENT PLACED AND WITNESSED _9/3/71 F. J. Bray WITNESSES TO CORNER 5" H. Maple (N1/16) (BT) S 35° W, 3.2'  N
WITNESSES TO CORNER 5" H. Maple (N1/16) (BT) S 35° W, 3.2'
N T
N 5" B. Ash (N1/16) (BT) S 80° E, 8.3'
AND CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was placed midway and on line between the section corner to the north and the 1/4 corner to the south. Corner set four feet north of stream bank.

SURVEYOR'S SEAL

DISTRIBUTION:

SIGNED

REGISTERED LAND SURVEYOR

DATE \_

Frank J. Bray

County Courthouse Area Forester (Regions I & II) District or Region Surveyor Forestry Div., Lansing

R 4047

Rev. 10/68