

STATE OF MICHIGAN  
DEPARTMENT  
OF  
NATURAL RESOURCES

LAND CORNER RECORD

Delta COUNTY


T 43 N R 22 W

DESCRIPTION OF CORNER Section corner for Sections  $\frac{26}{25}$   
 $\frac{35}{36}$

CORNER MONUMENT 1" iron pipe with 1/4" aluminum cap

DATE MONUMENT PLACED AND WITNESSED 7/19/71 F. J. Bray

WITNESSES TO CORNER..... 7" Elm (S.26) (NBT) N 51° W, 35.0'



8" Elm (S.25) (NBT) N 66° E, 10.9'

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was replaced from two original B.T.s Cedar to southwest is rotted stump with overgrowth of notch and possible scribe marks. Cedar to northeast has faint B.T. marks visible.

SURVEYOR'S SEAL

DISTRIBUTION:

SIGNED Frank J. Bray  
REGISTERED LAND SURVEYOR  
Frank J. Bray

DATE 9-21-71

County Courthouse  
Area Forester (Regions I & II)  
District or Region Surveyor  
Forestry Div., Lansing

R 4047  
Rev. 10/68