## STATE OF MICHIGAN DEPARTMENT OF NATURAL RESOURCES

## LAND CORNER RECORD

DeltaCOUNTY	
T <u>43 N</u> R <u>22 W</u>	_
DESCRIPTION OF CORNER 1/4 corner for Sections 28/27	
CORNER MONUMENT 12" x 30" iron pipe buried in dirt road	
DATE MONUMENT PLACED AND WITNESSED 7/19/71 F. J. Bray	
WITNESSES TO CORNER 11" Elm (1/45) (NBT) N 68° W, 42.4'	
9" Elm (1/4s) (NBT) N 61° E, 19.7'	
AND  CIRCLE CORNER REGISTERED	_

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was replaced from Marcus McNabb's N.B.T. which now is a rotted birch stump. Noted in McNabb's notes as follows: Birch 16", N  $48^{\circ}$  E, 28.8 feet. No original evidence found.

SURVEYOR'S SEAL

DISTRIBUTION:

SIGNED

REGISTERED LAND SURVEYOR
Frank J. Bray

DATE

9-21-71

County Courthouse Area Forester (Regions I & II) District or Region Surveyor Forestry Div., Lansing

R 4047 Rev. 10/68