STATE OF MICHIGAN DEPARTMENT 0F NATURAL RESOURCES

LAND CORNER RECORD

·	Delt a	COUNTY
т	43 & 42 N R	22 M
DESCRIPTION OF CORNER West 1/16 corner for Sections 32	T43N R22W T42N R22W	
CORNER MONUMENT 1" iron pipe with 4" aluminum cap		
DATE MONUMENT PLACED AND WITNESSED 7/12/71 F. J. Bray		
WITNESSES TO CORNER 10" leaning Cedar (W1/16) (BT) N 33° W, 3.0'		
8" leaning Cedar (W1/16) (BT)	S 19° E, 26.3	1
TN2N R\$2W AND		
CIRCLE CORNER REGISTERED		

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was placed midway and on line between the section corner to the west and the 1/4 corner to the east.

SURVEYOR'S SEAL

DATE

DISTRIBUTION:

REGISTERED LAND SURVEYOR

Frank J. Bray

County Courthouse Area Forester (Regions I & II) District or Region Surveyor Forestry Div., Lansing

R 4047 Rev. 10/68