

STATE OF MICHIGAN
DEPARTMENT
OF
NATURAL RESOURCES

LAND CORNER RECORD

Delta COUNTY


T 43 N R 22 W

DESCRIPTION OF CORNER Section corner for Sections ^{27/26}~~34/35~~

CORNER MONUMENT 1" iron pipe with 4" aluminum cap

DATE MONUMENT PLACED AND WITNESSED 7/27/71

WITNESSES TO CORNER..... 1 1/2" Cedar with location posters S 87° W, 4.4'



10" Cedar (S.26) (NBT) N 57° E, 21.0'

11" Cedar (dead) (S.34) (NBT) S 59° W, 17.1'

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was replaced from an old wood post. Forest Service location posters facing corner. Cedar stub with signatures dating back to 1944. Corner checks well with corners in the area.

SURVEYOR'S SEAL

DISTRIBUTION:

SIGNED Frank J. Bray DATE 9-21-71
REGISTERED LAND SURVEYOR
Frank J. Bray

County Courthouse
Area Forester (Regions I & II)
District or Region Surveyor
Forestry Div., Lansing

R 4047
Rev. 10/68