

STATE OF MICHIGAN  
DEPARTMENT  
OF  
NATURAL RESOURCES

LAND CORNER RECORD

Delta COUNTY


T 43 & 42 N R 22 W

DESCRIPTION OF CORNER 1/4 corner for Sections  $\frac{32}{5}$  T43N R22W  
T42N R22W

CORNER MONUMENT 1" iron pipe with 4" aluminum cap

DATE MONUMENT PLACED AND WITNESSED 7/12/71 F. J. Bray

WITNESSES TO CORNER..... 9" Cedar (1/4S) (NBT) N 82° W, 10.3'



8" Cedar (1/4S) (NBT) S 07° E, 7.6'

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was replaced from an old woodpost. B.T. to the northwest is a down cedar with scribe marks on lower face. Cedar stump in rotted condition to northeast checks with original field notes in bearing and distance.

SURVEYOR'S SEAL

DISTRIBUTION:

SIGNED Frank J. Bray DATE 9-20-71  
REGISTERED LAND SURVEYOR  
Frank J. Bray

County Courthouse  
Area Forester (Regions I & II)  
District or Region Surveyor  
Forestry Div., Lansing

R 4047  
Rev. 10/68