

STATE OF MICHIGAN
DEPARTMENT
OF
NATURAL RESOURCES

LAND CORNER RECORD

Delta COUNTY


T 43 & 42 N R 22 W

DESCRIPTION OF CORNER Section corner for Sections $\frac{31}{32}$ T43N R22W
 $\frac{6}{5}$ T42N R22W

CORNER MONUMENT 1 $\frac{1}{4}$ " x 30" iron pipe buried in north-south gravel road

DATE MONUMENT PLACED AND WITNESSED 6/28/71 F. J. Bray

WITNESSES TO CORNER..... 7" Hemlock (NBT) N 80° E, 29.4'



4" Cedar (NBT) S 62° W, 27.6'

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was replaced from measurements made by Marcus McNabb in 1921. No original evidence found. Corner lies in \oslash of gravel road.

SURVEYOR'S SEAL

DISTRIBUTION:

SIGNED


REGISTERED LAND SURVEYOR
Frank J. Bray

DATE

9-20-71

County Courthouse
Area Forester (Regions I & II)
District or Region Surveyor
Forestry Div., Lansing

R 4047
Rev. 10/68