

STATE OF MICHIGAN
DEPARTMENT
OF
NATURAL RESOURCES

LAND CORNER RECORD

Delta COUNTY


T 43 & 42 N R 22 W

DESCRIPTION OF CORNER Section corner for Sections ^{32/33} T43N R22W
5/4 T42N R22W

CORNER MONUMENT 1" iron pipe with 4" aluminum cap

DATE MONUMENT PLACED AND WITNESSED 6/23/71 F. J. Bray

WITNESSES TO CORNER..... 8" Cedar (S.5) (NBT) S 85° W, 6.9'



5" Cedar (S.5) (NBT) S 21° W, 11.1'

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was replaced from a rotted down, scribed wood post. B.T. to southwest has overgrowth of scribe marks. Rotted stump to southeast in proper bearing and distance. Blazed cedar stub near.

SURVEYOR'S SEAL

DISTRIBUTION:

SIGNED

Frank J. Bray
REGISTERED LAND SURVEYOR
Frank J. Bray

DATE

9-21-71

County Courthouse
Area Forester (Regions I & II)
District or Region Surveyor
Forestry Div., Lansing

R 4047
Rev. 10/68