

STATE OF MICHIGAN
DEPARTMENT
OF
NATURAL RESOURCES

LAND CORNER RECORD

Delta COUNTY


T 43 & 42 N R 22 W

DESCRIPTION OF CORNER Section corner for Sections ^{35/36} T43N R22W
2/1 T42N R22W

CORNER MONUMENT 1" iron pipe with 4" aluminum cap

DATE MONUMENT PLACED AND WITNESSED 9/2/71 F. J. Bray

WITNESSES TO CORNER..... 7" H. Maple (S.36) (NBT) N 06° E, 27.8'



8" H. Maple (S. 1) (NBT) S 25° E, 50.8'

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was replaced from point of old rotted down post. This position checks well with other corners in the area. No original evidence found.

SURVEYOR'S SEAL

DISTRIBUTION:

SIGNED

Frank J. Bray
REGISTERED LAND SURVEYOR
Frank J. Bray

DATE

9-20-71

County Courthouse
Area Forester (Regions I & II)
District or Region Surveyor
Forestry Div., Lansing

R 4047
Rev. 10/68