## STATE OF MICHIGAN DEPARTMENT OF NATURAL RESOURCES

## LAND CORNER RECORD

	Delta	COUNTY
	T 43 & 42 N	R22 W
DESCRIPTION OF CORNER 1/4 corner for Sections 1 Than	R22W R22W	
CORNER MONUMENT 1" iron pipe with 4" aluminum cap		
DATE MONUMENT PLACED AND WITNESSED 9/2/71 F. J. Bray		
WITNESSES TO CORNER 6" Cedar (1/4S) (NBT) S 470	E, 15.0'	
7" Cedar (1/4S) (NBT) S 07° I	G, 19.1'	
TU2N R22W AND		

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was placed midway and on line between section corners to the east and to the west. No original evidence found.

SURVEYOR'S SEAL

DISTRIBUTION:

SIGNED

REGISTERED LAND SURVEYOR

DATE

9-20-71

Frank J. Bray

County Courthouse Area Forester (Regions I & II) District or Region Surveyor Forestry Div., Lansing

R 4047 Rev. 10/68