

STATE OF MICHIGAN
DEPARTMENT
OF
NATURAL RESOURCES
LAND CORNER RECORD

Delta & Alger COUNTY


44 N
T's 43 N R's 21 & 22 W

DESCRIPTION OF CORNER Town corner T44N-R22W 36/31 T44N-R21W
T43N-R22W 1/6 T43N-R21W

CORNER MONUMENT 2" O.D. pipe with 3½" brass cap

DATE MONUMENT PLACED AND WITNESSED 10/26/71 F. J. Bray

WITNESSES TO CORNER..... 6" Cedar (S.1) (NBT) S25°W, 33.2'



9" W. Birch (S.36) (NBT) N17°W, 14.6'

Fence corner with F.S. tag, south, 0.7'

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was re-witnessed as set by Alger County surveyor, November 2, 1917, initials H.J.H. and G.L.D. stamped on cap. McNabb found the above monument with cedar B.T. present in 1921. Cedar to northwest badly burned.

SURVEYOR'S SEAL

DISTRIBUTION:

SIGNED

Frank J. Bray
REGISTERED LAND SURVEYOR
Frank J. Bray

DATE

12-9-71

County Courthouse
Area Forester (Regions I & II)
District or Region Surveyor
Forestry Div., Lansing

R 4047
Rev. 10/68