## STATE OF MICHIGAN DEPARTMENT OF NATURAL RESOURCES

## LAND CORNER RECORD

		Delta & Alger COUNTY
		T's 44 & 43 N R 22 W
DESCRIPTION OF CORNER _	Section corner for Sections	34/35 Thhn-R22W 3/2 Th3N-R22W
CORNER MONUMENT 1" iron pipe with 4" aluminum cap		
DATE MONUMENT PLACED AND WITNESSED _11/10/71 F. J. Bray		
WITNESSES TO CORNER 10" W. Birch (S.35) (NBT) N62°E, 19.9'		
N P	11" Cedar (S.3) (NBT) S6	54°W, 22.41
Then R2DV	AND	
CIRCLE CORNER REGISTERED		

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was replaced from two original B.T.s. W. Pine to northeast and cedar to southeast. Both cut above top face with scribe marks plainly visible.

SURVEYOR'S SEAL

SIGNED

D REGISTERED LAND SURVEYOR

DATE

12**-**9-71

DISTRIBUTION:

Frank J. Bray

County Courthouse Area Forester (Regions I & II) District or Region Surveyor Forestry Div., Lansing