STATE OF MICHIGAN DEPARTMENT OF NATURAL RESOURCES

LAND CORNER RECORD

		Delta	COUNTY
	T	<u>43 K</u>	R's 22 & 23 4
DESCRIPTION OF CORNER	North 1/16 corner for Sections	T43N R23H 13/18	T43N R22V
CORNER MONUMENT 1" iron pipe with 4" aluminum cap			
DATE MONUMENT PLACED AND WITNESSED 10/14/71 F. J. Bray			
WITNESSES TO CORNER 16" Elm (N1/16) (BT) N28°E, 32.4'			
N 18 18 18 18 18 18 18 1	7" Balsam (N1/16) (BT) SL1°E,	18.7	
Th 3N R22W	AND		

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was placed midway and on line between the section corner to the north and the 1/4 corner to the south.

SURVEYOR'S SEAL

SIGNED

REGISTERED LAND SURVEYO

DATE _

12-9-<u>71</u>

DISTRIBUTION:

Frank J. Bray

County Courthouse Area Forester (Regions I & II) District or Region Surveyor Forestry Div., Lansing