

STATE OF MICHIGAN
DEPARTMENT
OF
NATURAL RESOURCES

LAND CORNER RECORD

Delta COUNTY


T 43 N R 's 22 & 23 W

DESCRIPTION OF CORNER 1/4 corner for Sections T43N R23W 13/18 T43N R22W

CORNER MONUMENT 1" iron pipe with 4" aluminum cap

DATE MONUMENT PLACED AND WITNESSED 10/14/71 F. J. Bray

WITNESSES TO CORNER..... 6" Cedar (1/8) (NBT) N50°E, 5.5'



7" Cedar (1/8) (NBT) S88°W, 18.1'

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was placed midway and on line between the section corners to the north and to the south.

SURVEYOR'S SEAL

DISTRIBUTION:

SIGNED Frank J. Bray DATE 12-9-71
REGISTERED LAND SURVEYOR
Frank J. Bray

County Courthouse
Area Forester (Regions I & II)
District or Region Surveyor
Forestry Div., Lansing

R 4047
Rev. 10/68