

✓

STATE OF MICHIGAN
DEPARTMENT
OF
NATURAL RESOURCES

LAND CORNER RECORD


Delta COUNTY
T 43 N R 22 W

DESCRIPTION OF CORNER Section corner for Sections 21/22
28/27

CORNER MONUMENT 1" iron pipe with 4" aluminum cap

DATE MONUMENT PLACED AND WITNESSED 10/7/71 F. J. Bray

WITNESSES TO CORNER..... 18" H. Maple (NBT) S86°W, 41.8'



6" Elm (NBT) S42°E, 47.2'

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was replaced from an iron rod with portion of chain. This rod checks well with Marcus McNabb's notes in 1929. Found rotted H. Maple stump which checks for bearing and distance as noted by McNabb.

SURVEYOR'S SEAL

DISTRIBUTION:

SIGNED Frank J. Bray DATE 12-9-71
REGISTERED LAND SURVEYOR
Frank J. Bray

County Courthouse
Area Forester (Regions I & II)
District or Region Surveyor
Forestry Div., Lansing

R 4047
Rev. 10/68