

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 43-44 N.R. 22W

Delta-Alger COUNTY


DESCRIPTION OF CORNER 1/4 Corner between Sections 5-32

CORNER MONUMENT 1" pipe with 4" brass cap.

DATE MONUMENT PLACED AND WITNESSED 7-7-61 with J. Bastian, Asst. D. F.

WITNESSES TO CORNER..... 6" Cedar (1/4 S NBT) S40°E 29 links

6" Cedar " " N89°W 22 links



CIRCLE CORNER REGISTERED

AND

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was replaced at iron pipe and wood post set by unknown surveyor. Found one cedar B.T. bearing N77°E 39 links.

Corner lies in wet swamp.

SURVEYOR'S SEAL

SIGNED Billy D. Buckler DATE March 13, 1962
REGISTERED LAND SURVEYOR
Billy D. Buckler